


## Southeast Resiliency Academy

Session #6

Your New Construction Portfolio































#### Trifecta, since 2003









Over 2 Million Square Feet of certified LEED Projects



Over 4 Million Square Feet of Green Globes or FGBC Commercial



Over 30,000 acres of certified Green Developments







• USGBC, FGBC, NAHB, Green Globes



Host Discovery Channel's PROJECT EARTH



Florida Contractor #1330049






















#### Before & After

Opa Locka FL

































#### Sustainability









#### Sustainability versus Resilience

#### Sustainability

- Energy Use Reduction (Efficiency)
- Water Use Reduction
- Renewable Energy Production
  - Solar, Wind, Hydro
- Rapidly Renewable
- Recycled & Local Materials
- Community Responsibility
- Transportation Access
- Indoor Environmental Quality
- Infill, Density, Redevelopment

- ✓ Energy Independence
- waterIndependence
- ✓ Renewable Resources
- ✓ Long Term Environmental Effects
- ✓ Community Support
- ✓ Resource Storage

#### Resilience

- Multiple Diverse Energy Sources
- Multiple Water Sources
- Rainwater Harvesting, Wells, Desalinization
- Disaster Mitigation
- Elevated FFE above Flood Plain
- Non Coastal Construction
- Passive Systems
- Redundant Systems





#### A "Noun"

# What is Green Building?































# What is Green Building?























### Buildings have 3 Systems



- Windows
- Doors
- Roofs
- Walls






























#### Buildings have 3 Systems



- HVAC
- Lighting
- Water Heating
- Plug Loads
- Process Loads

























#### Buildings have 3 Systems



- Come in building, turn things on
- And sometimes off
- Leave door and windows open
- Require heat, light, air...

























#### Residential Energy Use – Florida





















#### What is a HERS Index?

#### **Confirmed Rating** RESNET Registration No.: 791674037

Lennar Homes - SW Florida 13520 Saw Palm Creek Trail Bradenton, FL 34211

\$0

Design: Sarasota, FL TMY: SARASOTA\_BRADENTON, FL

Title: Savanna at Lakewood Ranch Lot 109

#### **HOME ENERGY RATING GUIDE** \$1190

Reference \$1790

nual Energy Cost:	This Home	Savings
Electricity	\$ 975	\$ 502
Natural Gas	\$ 215	\$ 98
LPG	\$ 0	\$ 0
Fuel Oil	\$ 0	\$ 0
On-Site Power	\$ 0	\$ 0

Totals:		\$ 1190	\$ 600		
HERS® Index					
_		150	More En	ergy	
F		140			
Existing Homes		130			
		120			
Reference		110			
Home		100			
		90 80		This	
		70			
		60	—	62	
		50	-	lome	
		40			
		30			
		20			
Zero Energy Home		10 <b>O</b>			
©2013 RESNET		•	Less En	ergy	

Annual Energy Use:	This Home	Savings
Electricity (kWh/y)	8516	4388
Natural Gas (therms/y)	120	54
LPG (gal/y)	0	0
Fuel Oil (gal/y)	0	0
On-Site Power (kWh/y)	0	0

Innual Emissions:	This Home	Savings
CO2 (tons/y)	6	3
SO2 (lb/y)	19	10
NOx (lb/y)	1120	511




Ryan McCracken	4281370			
Certified Rater	I.D. Number			
Ryan McCracken	6/28/2017			
Signature	Date			
The Home Energy Rating Standard Dis	closure for this home			

is available from the Rating Provider. Questions or complaints regarding this Rating may be directed to:

SkyeTec Energy Rating Services 1679 Clearlake Road Cocoa, FL 32922-5703 phone: (321)638-1492 e-mail: engauge@fsec.ucf.edu www.energygauge.com/usares/

HERS and RESNET are Trademarks of Residential Energy Services Network, Inc. (www.resnet.us) EnergyGauge is a Trademark of the Florida Solar Energy Center (www.fsec.ucf.edu)










### HERS – Home Energy Rating System





# Improve Insulation



















#### **Roof Color Matters**

















- Solar Heat Gain Coefficient
- Tint (SHGC)
- Frame and glazing options aesthetics (U)
- Insulated glass climate or sound (U)
- Low-E glass "window radiant barrier" (U)
- Low-conductance gas fillings (U)
- Composite spacers thermal breaks


WINDOWS	U-		
CLIMATE ZONE	FACTOR <sup>1</sup>	SHGC <sup>2</sup>	
Northern	≤0.27	Any	Prescriptive
	=0.28	≥0.32	Equivalent
	=0.29	≥0.37	Energy
	=0.30	≥0.42	Performance
North Central	≤ 0.30	≤ 0.40	
South Central	≤ 0.30	≤ 0.25	
Southern	≤ 0.40	≤ 0.25	



Windows



























#### **Appliances and Controls**






















If your water heater is more than 10 YEARS OLD, upgrade to an ENERGY STAR® certified model!



















#### Proper Pressure Balance








### Small Air Leaks Add Up



#### Example:

• Negative pressure from bath fan






















### And We Have Holes...Airflow Holes

















# Infiltration












# **Building Envelope**




















#### Air ALSO Carries Moisture



- Air holds moisture
- Air moves due to pressure differences
- Air carries moisture into building

I" x I" hole






**OVER 18 Gallons of Water** During cooling season



#### Moisture Movement







#### Our Biggest Issue - Moisture
















Durability, Doability













### Biggest Impact On Energy Efficiency










**Appliances** 









Controls

















# Blue is the New Green Water Conservation








3%

#### **Water Consumption**









2.0 gpm

1.28 gpf (350 MaP)

1.5 gpm



EPA Policy 1991

Showers: 2.5 gpm

Toilets 1.6 gpf

Faucets: 2.5






Shower: As low as 1.5gpm

WC: Dual Flush Lav: 0.5 gpm











### Next Generation









# Dual Flush













# Install Water Saving Toilets

MaP Scoring Guide

Highly Recommended Great Flushing Performance	Recommende Strong Flushing	New years and the second	Acceptable Minimum	Not Recommended Poor Flushing Performance
1,000g-600g	600	g-350g	350g-250g	250g-0g
Weight Equivalents:	1,000g = 35 ounces	600g = 21 ounces	350g = 12 ou	inces













# Drought Tolerant Vegetation

















































# Cisterns





# Cistern - Rainwater Harvesting


































#### Indoor Environmental Quality












Lighting



Thermal comfort




Moisture control







### Filters


















MERV Rating:	0.3-1.0 μm	1.0-3.0 μm	3.0-10.0 μm
MERV 1	Under 20%	Under 20%	Under 20%
MERV 2			Under 20%
MERV 3			Under 20%
MERV 4			Under 20%
MERV 5			20% - 34%
MERV 6			35% - 49%
MERV 7	Under 20%	Under 20%	50% - 69%
MERV 8	Under 20%	Under 20%	70% - 85%
MERV 9	Under 20%	Under 50%	Above 85%
MERV 10	Under 20%	50% - 64%	Above 85%
MERV 11	Under 20%	65% - 79%	Above 85%
MERV 12	Under 20%	80% - 90%	Above 90%
MERV 13	Under 75%	Above 90%	Above 90%
MERV 14	75% - 84%	Above 90%	Above 90%
MERV 15	85% - 94%	Above 95%	Above 90%
MERV 16	Above 95%	Above 95%	Above 90%
MERV 17	99.97%	Above 99%	Above 99%
MERV 18	99.997%	Above 99%	Above 99%
MERV 19	99.9997%	Above 99%	Above 99%
MERV 20	99.99997%	Above 99%	Above 99%





















#### **Materials Selection**







Renewable



Sustainable



**Durability** 



Recyclability



Recycled content materials



Purchase local materials



Engineered products













#### Natural Disasters


























































#### www.trifectaconstruction.com

(239) 229 - 3177

Dr. Jennifer Languell

